

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-008039**Date Inspected:** 14-Jul-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 1900**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 700**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Li Yang**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Tower components**Summary of Items Observed:**

On this date CALTRANS OSM Quality Assurance (QA) Inspector, Dilip Chakrabarti was present during the times noted above for observations relative to the work being performed.

Bay# 10-Tower Assembly:

This QA Inspector randomly observed the following work in progress:

Ultrasonic Testing (UT):

This QA inspector performed Ultrasonic Testing (UT) of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL-6027 UT report on this date.

The member and the weld designations are as follows:

Sl # Section # Weld # Green Tag # Location

1. NSD1- FCSA4-1C/C 04 A,B NA NA

2. NSD1- FCSA4-1A/C 53 A,B NA NA

3. NSD1-TL8 B/L 03 A,B NA NA

SAW Process:

Welding of weld joint# 35B located on PCMK SSTL-1 B/F. Welder is identified as 207745. ZPMC QC is identified as Zong Yi. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2221-C-U2b-S.

FCAW Process:

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Welding of weld joint# 1 located on PCMK NSD1 A166-J/J. Welder is identified as 053116. ZPMC QC is identified as Li Peng Fei. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2233-B-T-U2a-F-1.

Welding of weld joint# 5 located on PCMK NSD1 A166-J/J. Welder is identified as 054069. ZPMC QC is identified as Li Peng Fei. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2233-B-T-U2a-F-1.

Unless otherwise noted, all work observed on this date appeared to be generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversation

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Serge Sinevod 134-8257-0045, who represents the Office of Structural Materials for your project.

Inspected By:	Chakrabarti,Dilip Kumar	Quality Assurance Inspector
----------------------	-------------------------	-----------------------------

Reviewed By:	Clifford,William	QA Reviewer
---------------------	------------------	-------------
